

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T...34 NR...1 E...  
T 34 NR 1 W

----- Cheboygan ----- COUNTY

DESCRIPTION OF CORNER ~~Section Corner common to Sections 30, 31, 25, 36~~ . . .

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap . . .

WITNESSES TO CORNER 6" Spruce - N 54 W - 20 Links . . .

6" Spruce - N 84 E - 33 Links . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Corner had been previously located and perpetuated by unknown Surveyor. Two original B.T.'s in place, in poor condition.

Corner was placed and witnessed August 22, 1951.

SURVEYORS SEAL

SIGNED *John C. G. G. G.* DATE 11/23/51  
REGISTERED LAND SURVEYOR