

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 34 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 23-24

CORNER MONUMENT Set 1" pipe with aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6-20-67

WITNESSES TO CORNER.....



12" W. Pine S 20 W 16.9"

9" R. Pine S 48 E 15.9"

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement between section corners during a retracement in this area. Could not identify U.S. evidence. Falls on edge of lake approximately as called for in U.S. record.

SURVEYOR'S SEAL

SIGNED *Kevin J. Ostling* DATE 6-21-67
REGISTERED LAND SURVEYOR #10068