MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T.M. NR.1.W.

			ChebayganCOUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Sections 25 & 35
DESCRIPTION	OF	CORNER	MONUMENT_1#_Pipe.with_4#_Brass_cap
WITTNESSES	то	CORNER	_ St Red_Oak = 8 50 R = 53 Links
			_ St Bed Oak - N. 53 F - St Idnka

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey orew, while making a partial reservey of this Township. Corner had been previously located and perpetuated by unknown Surveyor. Two original B.T.'s in place, badly burned.

Corner was placed and witnessed August 22, 1951.

SURVEYOR'S SEAL

SIGNED SIGNED LAND SURVEYOR MATE 11/23/51