

SURVEY & REMONUMENTATION

MAY 25 1997
 COMMISSION

**RE MONUMENTATION
 LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970**

RECEIVED FOR RECORD

96 NOV 25 PM 1:00

James Spray
 CLERK/REGISTER
 CHEBOYGAN COUNTY, MICHIGAN

For corners in
Cheboygan Located In: _____ Corner Code # _____
 (County)

1. Public Land Survey	T <u>34N</u> R <u>3W</u>	M-13
	T _____ R _____	_____
	T <u>34</u> R <u>2W</u>	<u>A-13</u>
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, Brian K. Fullford, in a field survey on August, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	10	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O.	1973 Recorded Survey	1976 Unrecorded Survey	1995 Unrecorded LCRC
Set Township Corner	Liber 336, Page 433	By George Henning #2240	By Norm Quaine #33984
10" Sugar N25°E 12 Links	By R.C. Dunn #12020	1" Pipe in 2" Pipe	1" Pipe inside 2" Pipe
8" Sugar S65°W 10 Links	Survey Showing Tie to Section Corner	MSHD Witness Tags	N76°E 15.11' 11" Spruce
			S73°E 23.35' 9" Ironwood
			S44°E 23.22' 17" Aspen
			S10°W 19.10' 22" Aspen

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" Pipe inside 2" Pipe
 11" Spruce N76°E 14.93'
 9" Ironwood S73°E 22.53'
 17" Aspen S44°E 21.85'
 22" Aspen S10°W 18.02'



LIBER 010 PAGE 203

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-13 Found 1" Pipe Inside 2" Pipe #15410. Replaced with 5/8" x 36" Bar with Remonumentation Cap. Accepted as a careful & faithful re-establishment of the position of the original corner.

11" Spruce N76°E 14.93'
 9" Ironwood S73°E 22.53'
 17" Aspen S44°E 21.85'
 22" Aspen S10°W 18.02'

THIS CORNER IS ALSO DESIGNATED AS CORNER CODES #A-13, IN T34N-R2W, #A-1, IN T33N-R2W AND #M-1, IN T33N-R3W.

Signed by Brian K. Fullford
 Surveyor's Michigan License No. 41099
 Brian K. Fullford, PS

Date 10/22/96

