

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 NR. 2 W

Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 4-5-8-9

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap, at base
of 12" B. Oak

WITNESSES TO CORNER

7" W. Pine	-	N78E	-	57 links
5" W. Pine	-	S5E	-	39½ links
12" W. Oak	-	N48W	-	46½ links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by Forestry Division survey crew while making a retracement in this area. Set corner from stumps of government BTs. Remains in place for all three witness trees, with possible evidence of face on SE Y. Pine. Corner checks for line and distance over good corners east and south.

Corner was placed and witnessed October 20, 1960.

SURVEYORS SEAL

SIGNED *Kenneth J. Ostling* DATE 10/25/60
REGISTERED LAND SURVEYOR