

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 NR. 2 W. . . .

Cheboygan

COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 8 and 9

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap,  
6" below surface

WITNESSES TO CORNER

7" W. Oak	*	S71E	-	43 1/2 links
6" W. Oak	-	N4E	-	64 1/2 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement between section corners by Forestry Division survey crew while making a survey in this township. Could not positively identify government BTs, one of which probably fell in pipeline. Corner falls on east edge of pipeline ROW.

Corner placed and witnessed October 26, 1960

SURVEYORS SEAL

SIGNED *Kenneth J. Ostling*  
REGISTERED LAND SURVEYOR

DATE 12/6/60