

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 NR. 2 W.

Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 4 and 9

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

5" Spruce - N55W - 15½ links

12" Cedar - S29E - 24½ links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a retracement in this area. Restored corner from original BT stumps- both in place with good faces and excellent marks on SE BT.

Corner was placed and witnessed September 23, 1960.

SURVEYORS SEAL

SIGNED Kenneth J. Ostling DATE 9/27/60  
REGISTERED LAND SURVEYOR