

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34. NR. 2 W.

Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to sections 15 and 16

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

8" B. Oak 0 S29W - 56 links

7" J. Pine - N66W - 34 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by Forestry Division survey crew while making a partial retracement of this township. Set corner from stumps of original BTs, the SW Y. Pine in place with good face, the NE J. Pine slab with evidence of both faces. Very good original corner.

Corner was placed and witnessed December 8, 1960.

SURVEYORS SEAL

SIGNED

Kenneth J. Ostling
REGISTERED LAND SURVEYOR

DATE 12/23/60