

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 34 .. NR .. 2 .. W ..

Cheboygan

COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ corner common to Sections 5 and 6

DESCRIPTION OF CORNER MONUMENT $\frac{1}{2}$ " pipe with $\frac{1}{2}$ " brass cap

WITNESSES TO CORNER

10" J. Pine - N30E - $41\frac{1}{2}$ links

8" J. Pine - S29E - 32 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey in this township. Found a $\frac{1}{2}$ " iron pipe at corner, in line with centerline of road west and south. Unable to identify government BTs but corner appears to have been accepted and was considered best available evidence.

Corner was placed and witnessed December 9, 1960.

SURVEYORS SEAL

SIGNED *Wesley J. Ostling*
REGISTERED LAND SURVEYOR

DATE 12/23/60