## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T.34 NR 2 //

				OHEDOAE		COUNT'
DESCRIPTION	OF CORNER	1/4 corne	r_comm	on to Se	ctions 2	and 3
DESCRIPTION (	OF CORNER	MONUMENT	<u>"pipe</u>	with 4"	brass_c	ap
WITNESSES TO	O CORNER	·				
		9" B. Oak	-	872E	_	21½ links
		10" B. Oak	<del>-</del>	841W	<b>.</b>	26 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement between section corners by Forestry Division survey crew while making a survey in this township. Unable to satisfactorily identify government BTs. Corner was set midpoint, on line, between section corners as prescribed by the government record.

Corner was placed and witnessed December 9, 1960.

SURVEYORS SEAL

SIGNED LEMENT SURVEYOR DATEL2/23/60\_