

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 35 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to sections 23 and 26

CORNER MONUMENT Set 5" squared cedar post

DATE MONUMENT PLACED AND WITNESSED Oct 13, 1965

WITNESSES TO CORNER.....



5" Ash S 48 W 21.6'

5" Ash S 25 E 23.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored from the original USBT stumps while making a survey in this area. SW stump in place with face and part of notch, NE tipped out and rotted.

SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE October 21, 1965  
REGISTERED LAND SURVEYOR #10068