

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 35 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 27-34

CORNER MONUMENT Set 1" pipe with 1/4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED April 27, 1966

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

10" Cedar N 85 E 16.5'

8" Cedar N 68 W 9.2'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this township. Found very old, scribed post at corner, with probable USBT stumps in place. Probably restored in early survey by County Surveyor.

SURVEYOR'S SEAL

SIGNED Kenneth Jostling DATE April 28, 1966  
REGISTERED LAND SURVEYOR #10068