

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 35 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER Sec. corner common to Sections 27-28-33-34

CORNER MONUMENT Set 1" pipe with 1/4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED _____

WITNESSES TO CORNER..... _____



CIRCLE CORNER REGISTERED

10" Cedar South 25.4'

7" Cedar S 83 W 17.8'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this township.
Found 1 1/4" pipe at fence corner which appears to conform to survey
pattern of Section 33. U. S. witnesses all gone, but appears
acceptable as proper location for corner.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE April 28, 1966
REGISTERED LAND SURVEYOR #10068