

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 35 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER M.C. common to Sections 26-27 on N. Side Stony Creek Flooding

CORNER MONUMENT Set 1" x 2 1/2" pipe

DATE MONUMENT PLACED AND WITNESSED June 16, 1966

WITNESSES TO CORNER.....



BT 6" Basswood N 49 E 17.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set to identify true section line, and to witness theoretical position of section corner which falls in flooded area.

Corner is 26.65 ch north of section corner in lake.

SURVEYOR'S SEAL

SIGNED Kenneth Ostling DATE June 20, 1966
REGISTERED AND SURVEYOR #10068