

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 35.. NR. 2 W. . .

Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 27-28-33-34

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

8" W. Oak	-	N28W	-	31 links
12" B. Oak	-	N39E	-	43 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey in this area. Found 1 $\frac{1}{4}$ " pipe in place, and very old scribed post. One possible OBT in place NE. Checks good for measurement west and reasonably well for line. Considered acceptable as section corner. Fence line runs southerly from corner.

Corner was placed and witnessed December 7, 1960.

SURVEYORS SEAL

SIGNED *Herbert J. Ostling*
REGISTERED LAND SURVEYOR

DATE 12/22/60