## **MICHIGAN** DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 35 NR 2 W

	-	Oheboyga	Δ 	COUNTY
DESCRIPTION OF CORN	ER 1/4 corner o	common to Sect	ions 33 an	a 34
DESCRIPTION OF CORNE	ER MONUMENT	pipe with 4"	_brass_cap	· 
WITNESSES TO CORNE				
	14" B. Oak	- 845E	- 17½	links
	12" B. Oak	- NSW	124	links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement, midpoint on line, between section corners by Forestry Division survey crew while making a survey in this tiwnship. Nothing left for J. pine BTs, but corner checks very good to stream crossing south.

Corner was placed and witnessed December 8, 1960.

SURVEYORS SEAL