

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T 35 NR 1 W      
T 35 NR 2 W

-----Cheboygan----- COUNTY

DESCRIPTION OF CORNER ~~Section-Corner common to Sections 13, 24, 18, 19~~-----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap-----

WITNESSES TO CORNER 8" Cedar - S 50 W - 68 Links-----

6" Cedar - N 50 E - 84 Links-----

6" Balsam - S 73 E - 57 Links-----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by the Forestry Division Survey crew, while running lines in this area. Corner had been previously perpetuated by unknown Surveyor, apparently about fifty years ago. One original B.T. in place, in poor condition.

Corner was placed and witnessed May 8, 1951.

SURVEYORS SEAL

SIGNED James C. DeLoater DATE 7/25/51  
REGISTERED LAND SURVEYOR