

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

CHEBOYGAN COUNTY


T 35 N R 3 W

DESCRIPTION OF CORNER Meander Corner between Secs. 24-25 on E Side of Burt Lake

CORNER MONUMENT Set Dept. Monument

DATE MONUMENT PLACED AND WITNESSED 6-27-69

WITNESSES TO CORNER.....



Spike in 22" W. Pine S 3 W 6.96'

Spike in 20" W. Pine N 59 E 13.75'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey of the Park Boundary. Found post bottom believed to be a recovery of the U.S. meander corner, previously identified in surveys by Doyle and Paddison.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE 7-2-69
REGISTERED LAND SURVEYOR #10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68