

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 36 NR. 1 E

Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 2-3-10-11

DESCRIPTION OF CORNER MONUMENT Left 3" pipe below surface of road

WITNESSES TO CORNER

<u>6" R. Pine</u>	-	<u>S51E</u>	-	<u>54.0 feet</u>
<u>24" W. Pine</u>	-	<u>N7W</u>	-	<u>46.0 feet</u>
<u>9" W. Pine</u>	-	<u>N74W</u>	-	<u>38.6 feet</u>

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey of Section 2. Found 3" pipe in place at intersection of roads and firelanes. Appears to have been used in road location and development. Checks good with meander corner and lake shore north, and was considered best available evidence of proper location.

Corner was witnessed May 26, 1960.

SURVEYORS SEAL

SIGNED

*Kenneth J. Osting*  
REGISTERED LAND SURVEYOR

DATE 6/9/60