

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 36. NR. 1 E.

Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 2 and 11 . . .

DESCRIPTION OF CORNER MONUMENT Left 3" pipe in place below surface

WITNESSES TO CORNER

8" R. Oak	-	S27E	-	22.6 feet
12" R. Oak	-	N46W	-	42.7 feet
6" R. Pine	✓	S44W	-	61.4 feet

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey of Section 2. Found a 3" pipe in place at intersection of firelines E-W and south. Cannot identify gov't BTs, but accepted this corner as best available evidence. Checks fairly good for midpoint, considering the terrain.

Corner was witnessed May 26, 1960.

SURVEYORS SEAL

SIGNED *Kenneth J. Oetting* DATE 6/9/60
REGISTERED LAND SURVEYOR