MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T 36 NR 1 E

		Cheboygan	COUNTY
DESCRIPTION OF CORNER	T/4 coluer com	won_to_Sections_1	_ and 2
DESCRIPTION OF CORNER	MONUMENT_Left	pipe in plac	ce_pelow_gurface
WITNESSES TO CORNER .			. .
	5" R. Oak	N38E	25.0 feet
	9" R. Oak	n36w	22.1 feet

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey of Section 2. Found 11 pipe in place below surface of N-S fireline. A large W. Pine stump in place for possible NE government BT. and this point checks good for measurement to high ridge 12.50 ch south as per government record. Checks for measurement north to Section corner.

Corner was witnessed May 26, 1960.

SURVEYORS SEAL

SIGNED SURVEYOR DA

DATE 6/9/60