

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T 36 NR 1 E  
T 37 NR 1 E

Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 1-2-35-36

DESCRIPTION OF CORNER MONUMENT Left 3" pipe in place below surface

WITNESSES TO CORNER

6" Maple	-	N26E	-	52.1 feet
8" W. Birch	-	N26W	-	61.4 feet
5" Maple	-	S66W	-	51.5 feet

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey of Section 2. Found a 3" pipe in place at fireline intersection. Unable to identify Hemlock government BTs but corner was considered acceptable since no better evidence could be found. Checks good with 1/4 corners east and west and south.

Corner was witnessed May 26, 1960

SURVEYORS SEAL

SIGNED *Timothy J. Ostberg* DATE 6/9/60  
REGISTERED LAND SURVEYOR