

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T 36 NR 1 E  
T 37 NR 1 E

Cheboygan COUNTY

DESCRIPTION OF CORNER East 1/8 corner common to Sections 2 and 35

DESCRIPTION OF CORNER MONUMENT 1 1/4" pipe, below surface

WITNESSES TO CORNER

9" Maple - - - - - 88W - - - - - 90.0 feet

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was corrected to its calculated true position by Forestry Division survey crew while making a survey of Section 2. Found 1 1/4" pipe in vicinity which obviously was set in error in previous survey. Placed pipe midpoint, on line between section corner and 1/4 corner.

Corner was set and witnessed May 26, 1960.

SURVEYORS SEAL

SIGNED

*Kenneth J. Ostling*  
REGISTERED LAND SURVEYOR

DATE 7/5/60