

SURVEY & REMONUMENTATION

FEB 26 1998

SECTION

CHEBOYGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Cheboygan
(County)

Located In:	Corner Code #
T36N R 3W	L-9
T___ R___	_____
T___ R___	_____
T___ R___	_____
S___ T___ R___	_____
S___ T___ R___	_____
S___ T___ R___	_____
S___ T___ R___	_____

- 1. Public Land Survey
- 2. Property Controlling in Section
- 3. Miscellaneous Property in Sec.

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Brian K. Fullford, in a field survey on Sept. 16, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- | | |
|------------------------------|----------------------------|
| G.L.O. | 1972 Orlando Doyle #7319 |
| 1855 Harvey Mellen | Set concrete monument |
| Set 1/4 Section Post | 24" Oak S 68° W 37.64' |
| 12" Y Pine N 23° W 63 lks | 30" Tw. Oak S 57° W 46.62' |
| 9" B. Oak S 88 3/4° W 62 lks | 10" Oak N 75° E 56.88" |

1993 David Grondin #39080
Found Concrete monument

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Found concrete monument and 3 witnesses.



LIBER **011** PAGE **22**

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-9 Placed remonumentation cap on monument, and is accepted as a careful and faithful perpetuation of the original corner.

- | | |
|----------------------------|---------------|
| 14" Oak N 75° E 45.67' | Set Tag 41099 |
| 3/4" Pipe S 81° E 32.93' | |
| 26" Oak S 68° W 37.64' | W/Tag |
| 35" Tw. Oak N 57° W 47.06' | Set Tag 41099 |
| 16' W of N/S two-track | |



Signed by Brian K. Fullford
Surveyor's Michigan License No. 41099

Date 11/21/97