

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD


T. 37 N.R. 1 E and 1 W.
T. 38 N.R. 1 E and 1 W.
Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 1 - 6 - 31 - 36

CORNER MONUMENT Left 4" iron pipe in place

DATE MONUMENT PLACED AND WITNESSED October 10, 1963

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

12" R. Pine S 37 W 3.0'

12" R. Pine N 11 E 25.1

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a retracement in this area. Found a 4" pipe in place, probably restored in a previous survey by Marcus Schaaf, R. L. S. Possible BT stumps in place. Appears acceptable as best available evidence of corner.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE December 11, 1963
REGISTERED LAND SURVEYOR #10,068