

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD


T. 37 N.R. 1 E  
T. 37 N.R. 1 W Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to sections 18 and 13

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED July 9, 1965

WITNESSES TO CORNER.....



24" R. Pine N 61 E 48.2 °

22" R. Pine S 43 E 47.7 °

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this area. Found 1 1/2" pipe at corner which was obviously established midpoint on line between section corners. No evidence to the contrary.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE October 18, 1965  
REGISTERED LAND SURVEYOR #10068