

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD


T. 37 N.R. 1 E
T. 37 N.R. 1 W Cheboygan COUNTY

DESCRIPTION OF CORNER Sec. corner common to sections 18, 19, 13, and 24

CORNER MONUMENT Left 1 1/2" pipe in place

DATE MONUMENT PLACED AND WITNESSED July 7, 1965

WITNESSES TO CORNER.....



2 1/2" R. Pine N 62 W 26.0'

12" Spruce S 34 E 16.7'

AND No marks

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this area. Found 1 1/2" pipe at corner as established in a previous survey of the meridian by unknown surveyor, possibly under the direction of Marcus Schaaf. All corners north and south appear to tie in with this corner and it appears to have been accepted locally. Considered best available evidence.

SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE October 18, 1965
REGISTERED LAND SURVEYOR #140068