

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 37 N.R. 1 E.


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 33 - 34

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED December 13, 1963

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

5" Cedar N 49 E 9.4'

10" Cedar S 34 W 21.8

AND

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This corner was set by proportionate measurement between section corners, mid-point on line, while making a survey in this area. Unable to identify anything for original evidence.

**SURVEYOR'S SEAL**

SIGNED *Kenneth J. Osling* DATE December 17, 1963  
REGISTERED LAND SURVEYOR # 10068