## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 37 N.R. 1 E

		Cheboygan	COUNTY
DESCRIPTION OF CORNER 1/4 corner common to sections 2	1 - 26	3	
CORNER MONUMENT Set 1" pipe - 4" brass cap			
DATE MONUMENT PLACED AND WITHESSED 8-8-63			
WITNESSES TO CORNER			
5" R. Pine - N 28 W	<del>-</del>	61.0	
5" R. Pine - S 65 W		51:•0	
CIRCLE CORNER REGISTERED			

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement, midpoint on line, between section corners while making a survey in this township. Remains of some stumps in vicinity but can identify rothing conclusive.

SURVEYOR'S SEAL

SIGNED Could felling 110068 DATE 9/18/63

REGISTERED LAND SURVEYOR