## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 37 K.R. 1 E

|   |          | Cheboygan    |      | COUNTY      |
|---|----------|--------------|------|-------------|
| DESCRIPTION OF CORNER 1/4 corner commo  | on to se | ctions 21-22 |      |             |
| CORNER MONUMENT Set 1" pipe with 4" b   | rass ca  | p            |      |             |
| DATE MONUMENT PLACED AND WITNESSED 8-8- | 63       |              |      | <del></del> |
| WITHESSES TO CORNER 12" W. Birch        |          | N 32 W -     | 22.5 |             |
| 5" Laple                                | <u>-</u> | 11 53 E      | 11.4 |             |
| CIRCLE CORNER REGISTERED                |          |              |      |             |

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement, midpoint on line, between Section Corners while making a survey in this township. Nothing left for OBTS.

SURVEYOR'S SEAL

SIGNED Mester Justicia #10068 DATE 9/18/63

REGISTERED LAND SURVEYOR