

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 37 N. R. 1 E


Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to sections 2-3 - 10-11

CORNER MONUMENT Post

DATE MONUMENT PLACED AND WITNESSED 8-21-63

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

8" Maple	-	N 19 E	-	17.6
7" Spruce	-	S 17 W	-	20.7
AND				
2 1/2" W. Pine Stp.	-	S 85 W	-	12.6

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a retracement in this township. Restored corner from stumps of USBTS. Both in place with evidence of face and notch. Also line tree stump in place N. E. & W. Good original corner.

SURVEYOR'S SEAL

SIGNED *Arnold Wilby* #10068 DATE 9/18/63
REGISTERED LAND SURVEYOR