

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 37. NR. 1. E. . .

----- Cheboygan ----- COUNTY

DESCRIPTION OF CORNER Section corner common to sections 20, 21, 22, 29 . . . . .

DESCRIPTION OF CORNER MONUMENT 1" Iron pipe with 4" Brass cap . . . . .

WITNESSES TO CORNER 6" Red Oak - S 65 P - 63 Links . . . . .

4" F. Birch - S 1 W - 41 Links . . . . .


18" Red Pine - N 30 W - 1.11 chains . . . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established, by proportionate measurement, by Forestry Division survey crew working in this Township. One probable R.T., still in place, but badly burned.

Corner was placed October 16, 1950.

SURVEYORS SEAL



SIGNED

*Dean C. DeLuca*  
REGISTERED LAND SURVEYOR

DATE 12/4/50