

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 37 N. R. 1 E


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 22 - 27

CORNER MONUMENT Set 1" pipe with 4" brass cap

DATE MONUMENT PLACED AND WITNESSED September 5, 1963

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

6" Aspen S 87 W 19.3'

Only thing near worth marking

AND

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This corner was restored while making a survey in this area. Set corner from SW USBT which is down but with good face and notch and in good condition. Definitely an original corner.

SURVEYOR'S SEAL

SIGNED Kenneth A. Oetting DATE December 11, 1963  
REGISTERED LAND SURVEYOR #10,068