Cons. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. \_\_37 \_\_\_ N.R. \_\_1 E

			Cheboygan		COUNTY
DESCRIPTION OF CORNER				34-35 on North	arm
of Twin Lal Corner Honument <u>Lu so</u>	ces, about 3 chai quare cedar post	ns South of	¿ correr		
DATE MONUMENT PLACED AND I	rithessed <u>12/1</u>	9/63			
WITNESSES TO CORNER					<u>.</u>
	l₄" Cedar	<u>11 39 E</u>	15.կ		
35	5" Cedar	S 61 E	27.4		
CIRCLE CORNER REGISTERED -	AMD				

## DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this area. Found a small squared post at corner as previously restored from b.S.E.T. which is still in place with good face. Area covered with water and unable to set marker per anently. Checks good with corners south.

SURVEYOR'S SEAL

SIGNED MULLE DECLARE SURVEYOR #16,068 DATE DEC