Cons. 4047 Rev. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 37 M.R. 1 E

|                             |                      |                 | Cheboyg <b>an</b> | COUNTY |
|-----------------------------|----------------------|-----------------|-------------------|--------|
| DESCRIPTION OF CORNER       | corner common        | to Sections     | 27-34             |        |
| CORNER MONUMENT             | " pipe with 4" alumi | inum cap        |                   |        |
| DATE MONUMENT PLACED AND WI | TNESSED              | 0/63            |                   |        |
| WITHESSES TO CORNER         |                      | <del></del>     |                   |        |
| _                           | 7" Basswood          | <u> 11 69 E</u> | 7•9               |        |
|                             | 5" H. Laple          | S 32 W          | <u> </u>          |        |
| CIRCLE CORNER REGISTERED -  | D                    |                 |                   |        |

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement, mid-point on line, between section corners. Nothing for U. S. evidence, or a previous corner.

SURVEYOR'S SEAL

SIGNED Lewel Detling DATE December 31, 196