

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 37 N. R. 1 E.


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 19 - 30

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED December 11, 1963

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

6" Cedar S 13 W 14.7'

6" Balsam N 21 W 25.2

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement, ~~between~~, between section corners, while making a survey in this area. Nothing for U. S. evidence;

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE December 17, 1963
REGISTERED LAND SURVEYOR #10,068