

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD


T. 37 N.R. 1 W.
T. 38 N.R. 1 W. Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 1 - 36

CORNER MONUMENT Set 1" pipe with 4" brass cap

DATE MONUMENT PLACED AND WITNESSED October 30, 1963

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

5" R. Pine N 72 E 60.4'

5" R. Pine N 46 W. 74.6'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement, midpoint on line between section corners, while making a survey in this township. Nothing left for U. S. BPs or a previous corner.

SURVEYOR'S SEAL

SIGNED *Levitt J. Ostling* DATE December 16, 1963
REGISTERED LAND SURVEYOR