## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 37 N.R. 3 W

		Chebo	Cheboygan		
DESCRIPTION OF CORNER 1/4	corner at center	of Section 7			
CORNER MONUMENT 18 x21/11	pipe	· · · - · · · · · · · · · · · · · · · ·			
DATE MONUMENT PLACED AND WI	THESSED 2/22/62			<u> </u>	
WITHESSES TO CORNER					
<b>N</b> -	6" Cedar	- N12E	-	20.5 feet	
<b>5</b>	4" Cedar	<b>s</b> 87W		17.8 feet	
CIRCLE CORNER REGISTERED -	D				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set according to survey procedure for the subdivision of sections while making a survey of Section 7. Set corner at the intersection of the true 1/4 lines.

SURVEYOR'S SEAL

SIGNED Leweth Vetling DATE 3/9/62
REGISTERES LAND SURVEYOR