

**CHEBOYGAN COUNTY REMONUMENTATION CORNER**

**LAND CORNER RECORDATION CERTIFICATE**  
 Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

CHEBOYGAN Located In: \_\_\_\_\_ Corner Code # \_\_\_\_\_  
 (County)

1. Public Land Survey      36" 2W  
    T 37NR 2W  
    T \_\_\_\_\_ R \_\_\_\_\_  
    T \_\_\_\_\_ R \_\_\_\_\_  
    T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling      S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 in Section                      S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous              S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 Property in Sec.                S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

RECEIVED FOR RECORD 12-18-97  
 at 1:21 O'Clock A M

*Joanne Spray*  
 CLERK/REGISTER  
 CHEBOYGAN COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

I, JAMES H. GRANGER, in a field survey on JULY 15, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6	5	4	3	2	1						
3													
4		7	8	9	10	11	12						
5													
6		18	17	16	15	14	13						
7													
8		19	20	21	22	23	24						
9													
10		30	29	28	27	26	25						
11													
12		31	32	33	34	35	36						
13													

A. Description of original monument and accessories and/or subsequent restoration:

- C-1 1840 Original Survey                      36" Pine Corner  
    John Mullett
- 1972 Survey                                      Metal Monument  
    Orlando Doyle #7319
- 1977 LCRC                                        Concrete Monument  
    Orlando Doyle #7319



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- C-1 Found concrete monument and 2 existing witnesses grown over. Set remonumentation cap on concrete monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- C-1 Concrete Monument with Remonumentation Cap  
     16" Poplar    N19°W 86.42'    Set tag #16041  
     PP            N19°E 115.65'    Set tag #16041  
     24" Maple    S62°E 18.41'    Set tag #16041  
     PP            S57°W 48.08'    Fd tag #41099

LIBER **011** PAGE **25**

Signed by James H. Granger  
 License No. 16041

Date Nov. 17, 1997 Surveyor's Michigan

