

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 38 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner at center of Sec. 26

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 4-28-67

WITNESSES TO CORNER.....



5" Cedar S 41 W 9.55'

4" Cedar N 32 W 7.9'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set at intersection of North-South and East-West $\frac{1}{4}$ lines.

SURVEYOR'S SEAL

SIGNED _____ DATE 5-31-67
REGISTERED LAND SURVEYOR #10068