

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 38 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER Sec. corner common to Sections 23-24-25-56

CORNER MONUMENT Left 4" concrete monument in place

DATE MONUMENT PLACED AND WITNESSED 4-25-67

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

5" Cedar S 20 E 3.8'

5" R. Maple N 71 E 6.2'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this township. Corner set by unknown local surveyor. Probably a perpetuation of corner set by David Bowen, County Surveyor, in 1924.

SURVEYOR'S SEAL

SIGNED \_\_\_\_\_ DATE 5-25-67  
REGISTERED LAND SURVEYOR #10068