

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 38 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER Sec. corner common to Sections 22-23-26-27

CORNER MONUMENT Left 4" iron pipe in place

DATE MONUMENT PLACED AND WITNESSED 4-26-67

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

6" Cedar S 72 E 10.5'

12" B. Spruce S 62 W 22.55'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this township. 4" iron pipe was set by David Bowen, Cheboygan County Surveyor in 1924. Unable to positively identify U.S. evidence, but has the weight of long standing and acceptance.

SURVEYOR'S SEAL

SIGNED _____ DATE 5-31-67
REGISTERED LAND SURVEYOR #10068