

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 38 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 26 - 35

CORNER MONUMENT Set 1" pipe with 4" alum. cap.

DATE MONUMENT PLACED AND WITNESSED 4-24-67

WITNESSES TO CORNER.....



5" Cedar N 8 W 6.2'

6" W. Spruce N 80 E 10.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this township. 5" squared scribed post. Probably a perpetuation of corner as set by David Bowen, County Surveyor in 1924. Corner accepted by local surveyors.

SURVEYOR'S SEAL

SIGNED _____
REGISTERED LAND SURVEYOR #10068

DATE 5-31-67