

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 38 N.R. 2 W.


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 20 - 29

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED April 17, 1963

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

7" Cedar S 67 W 16.9'

6" Cedar S 61 E 15.6'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement, midpoint on line, between section corners while making a survey in this township. Unable to locate a previous corner, or conclusively identify the USBTs although several stumps in vicinity.

SURVEYOR'S SEAL

SIGNED *Kenneth Ostling* DATE April 23, 1963  
REGISTERED LAND SURVEYOR #10068