

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 38 N.R. 2 W.


Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 16 - 17 - 20 - 21

CORNER MONUMENT Set 1" pipe with 4" brass cap

DATE MONUMENT PLACED AND WITNESSED April 17, 1963

WITNESSES TO CORNER.....



18" Spruce S 87 W 97.6'

7" Spruce N 6 E 99.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a partial resurvey of this township. Found a 3/4" iron bar and scribed post in place at fence line. Obviously used in surveys to the south. Nothing left for USBTs.

Bowen claims to have identified BTs in early 1900 survey. Falls on line over corners to south.

SURVEYOR'S SEAL

SIGNED Kenneth J. Pethley DATE April 23, 1963
REGISTERED LAND SURVEYOR #10068