

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 38 N.R. 3 W.  
T. 39 N.R. 3 W.


Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 33 - 34 - 3 - 4

CORNER MONUMENT Set 1" pipe with 4" brass cap

DATE MONUMENT PLACED AND WITNESSED April 22, 1964

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

6" Cedar N 78 W 10.5'

6" Cedar N 55 E 36.0'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey of this area. Found 3/4" pipe in place as previously established by unknown surveyor. Old township road grades E-W-S. Remains of two probable BTs in place.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE June 24, 1964  
REGISTERED LAND SURVEYOR # 10068