

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD


T. 38 N.R. 3 W.
T. N.R. W.
Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 13 - 24

CORNER MONUMENT Set 1" pipe with 4" brass cap

DATE MONUMENT PLACED AND WITNESSED May 20, 1963

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

8" Cedar N 51 E 1.6'

7" Cedar N 29 W 11.2'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement, midpoint on line, between section corners while making a survey in this area. Nothing positive for U. S. BTs.

SURVEYOR'S SEAL

SIGNED Kenneth J. Osting DATE June 24, 1963
REGISTERED LAND SURVEYOR #10078