

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 38 N.R. 3 W.


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 13 - 14

CORNER MONUMENT Set 1" pipe with 4" brass cap

DATE MONUMENT PLACED AND WITNESSED May 21, 1963

WITNESSES TO CORNER.....



7" Cedar N 64 E 41.7'

10" Maple N 47 W 36.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement, midpoint on line, between section corners while making a survey in this area. Nothing positive for U. S. B.Ts.

SURVEYOR'S SEAL

SIGNED *Kenneth Heston* DATE June 24, 1963
REGISTERED LAND SURVEYOR #10068