

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 38 N. R. 3 W.


Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 23 - 24 - 25 - 26

CORNER MONUMENT Drove 1/2" iron bar in road

DATE MONUMENT PLACED AND WITNESSED May 21, 1963

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

8" Maple N 7 E 27.5'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored while making a survey in this area to control other corner placement. Any previous corner lost in road construction. Set corner on line over 1/4 and Section corner south, in center of E - W county road. This checks fairly well with fence line north and falls in line with old road grade east.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Osting* DATE June 24, 1963
REGISTERED LAND SURVEYOR #10068