

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 39 N.R. 3 W.


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 29 - 30

CORNER MONUMENT Drove 1" x 24" pipe below surface

DATE MONUMENT PLACED AND WITNESSED April 22, 1964

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

14" Spruce S 50 E 38.4'

6" Cedar N 79 W 35.9'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this area. Found 1/2" pipe, bent over, in center N - S road as established in previous survey. Considered acceptable as proper location for corner.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE April 22, 1964
REGISTERED LAND SURVEYOR #10068